

Work Order ID 59416

Friday, June 04, 2010 9:57:42 AM

Page 1

Item ID: D407-559-113

Accept

Setup Start

Revision ID:

Stop

Item Name: Bearpaw, Large

Start Date: 6/4/2010 Start Qty: 1.00

Cust Item ID:

Required Date: 6/11/2010 Req'd Qty: 1.00

Customer:

Reference: Return 2010 RA110039 /NCR10-020

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

QC: _____ Date: 10-06-04 SPC (Y/N): _____ Date: _____

Stop

| Sequence ID/ Work Center ID | Operation Description | Set Up/ Run Hours | Tool ID | Tool # | Plan Code | Accept Qty | Reject Qty | Reject Number | Insp. Stamp |
|--------------------------------|--------------------------|----------------------|---------|--------|--------------|---------------|---------------|------------------|----------------|
|--------------------------------|--------------------------|----------------------|---------|--------|--------------|---------------|---------------|------------------|----------------|

| Draw Nbr | Revision Nbr |
|--------------|--------------|
| D4010 | D |
| IIN-D206-559 | K |

100

0.00



QC

Quality Control

Memo

Original B53259.
Scrap & destroy parts.

0.00

SAD 16-06-08

110

QC21- Final Inspection - Work Order Release

0.00



QC

Quality Control

Memo

0.00



10/06/14

ME

10-6-14